2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado

2012 Engine

Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado

REPAIR INSTRUCTIONS - ON VEHICLE

DRIVE BELT REPLACEMENT

Removal Procedure




Fig. 1: View Of Drive Belt Routing & Pulleys (With A/C)
Courtesy of GENERAL MOTORS COMPANY

- 1. Install a 3/8 inch breaker bar into the drive belt tensioner (7) and rotate the tensioner (7) clockwise, enough to relieve the tension on the drive belt (1).
- 2. Slide the drive belt (1) from the water pump pulley (2).
- 3. Allow the drive belt tensioner (7) to return to the relaxed position.
- 4. Remove the drive belt (1) from the remaining pulleys.

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado





Fig. 3: View Of Drive Belt Tensioner
Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the drive belt. Refer to **Drive Belt Replacement**.
- 2. Inspect the drive belt. Change the drive belt as necessary.
- 3. Using a wrench loosen and remove the drive belt tensioner bolt.
- 4. Remove the drive belt tensioner.

Installation Procedure

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado



<u>Fig. 10: Locating Installation Start Bolt - Left</u> Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to Fastener Caution.

- 3. To aid in the installation of the bolts, start a bolt in position (1) first. Tighten the bolts to 50 N.m (37 lb ft).
- 4. Lower the engine.

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado




Fig. 21: Generator Mounting Bolt Tightening Sequence Courtesy of GENERAL MOTORS COMPANY

4. Install the generator bolts and tighten in sequence to 50 N.m (37 lb ft).

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado




Fig. 48: View Of Valve Springs & Retainers
Courtesy of GENERAL MOTORS COMPANY

14. Remove the valve spring retainer and valve spring.

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado




Fig. 66: Checking For TDC Position
Courtesy of GENERAL MOTORS COMPANY

39. First Method (continued) - When the piston is at TDC, the flats at the rear of the camshafts will be facing up and level when using a straight edge across the camshaft flats.

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado





Fig. 87: Exhaust Camshaft Sprocket Bolt Courtesy of GENERAL MOTORS COMPANY

11. Tighten the new exhaust camshaft actuator sprocket bolt.

Using J 45059 angle meter , tighten the exhaust camshaft actuator sprocket bolt to 25 N.m (18 lb ft) plus 135 degrees.



<u>Fig. 103: View Of Service Slot Plug</u> Courtesy of GENERAL MOTORS COMPANY

- 6. Install the service slot plug.
- 7. Lower the vehicle.
- 8. Install the drive belt. Refer to **Drive Belt Replacement**.
- 9. Install the radiator. Refer to **Radiator Replacement**.

CRANKSHAFT FRONT OIL SEAL REPLACEMENT

Tools Required

J 45951 Front Seal Installer

Removal Procedure

1. Remove the crankshaft balancer. Refer to **Crankshaft Balancer Replacement**.

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado

Removal Procedure




Fig. 119: Camshaft Holding Tool
Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the camshaft cover. Refer to **Camshaft Cover Replacement**.
- 2. Rotate the crankshaft in the engine rotational direction clockwise, until the #1 piston is at top dead center (TDC) on the compression stroke.
- 3. Using the timing mark on the intake camshaft sprocket as a reference, make a mark on the timing chain link adjacent to it.

WARNING: Refer to Camshaft Holding Tool Warning.

4. Install the **J 44221** camshaft holding tool to the rear of the camshafts.

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado




Fig. 130: View Of Timing Chain & Sprockets
Courtesy of GENERAL MOTORS COMPANY

- 11. Remove and discard the intake camshaft sprocket bolt.
- 12. Remove the intake camshaft sprocket.
- 13. Remove the timing chain.
- 14. Remove the crankshaft sprocket.

Installation Procedure

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado




Fig. 136: Camshaft Holding Tool Courtesy of GENERAL MOTORS COMPANY

12. Remove the **J 44221** camshaft holding tool from the camshafts.

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado




Fig. 150: Identifying Chain Alignment Links
Courtesy of GENERAL MOTORS COMPANY

- 5. Using the timing marks on the following as a reference, make a mark on the timing chain links (1) adjacent to them:
 - The exhaust camshaft position actuator sprocket
 - The intake camshaft sprocket
 - The crankshaft sprocket

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado





Fig. 161: View Of Upper Timing Chain Guide Courtesy of GENERAL MOTORS COMPANY

- 1. Remove the camshaft cover. Refer to **Camshaft Cover Replacement**.
- 2. Remove the upper timing chain guide bolts.
- 3. Remove the upper timing chain guide from the cylinder head.

Installation Procedure

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado



<u>Fig. 169: View Of Camshaft Cap Bolts</u> Courtesy of GENERAL MOTORS COMPANY

8. Alternately loosen the camshaft cap bolts a few turns at a time until all valve spring pressure has been released.

NOTE: Place the camshaft caps in a rack to ensure the caps are installed in the same location from which they were removed.

- 9. Remove the camshaft caps.
- 10. Remove the **J 44221** camshaft holding tool from the camshafts.

2012 Engine Engine Mechanical - 2.9L - Repair Instructions - On Vehicle - Canyon, Colorado




Fig. 192: View Of Engine Oil Pressure Switch Courtesy of GENERAL MOTORS COMPANY

CAUTION: Refer to <u>Component Fastener Tightening Caution</u>.

1. Install the engine oil pressure switch and tighten to 20 N.m (15 lb ft).