

## A4LD UPDATE HANDBOOK INDEX

BELL HOUSING (ENGINE SIZE) IDENTIFICATION .....	3
BELL HOUSING CHANGES .....	7
FRONT SEAL BLOW-OUT .....	8
PUMP PLATE DIFFERENCES .....	9
BELL HOUSING/PUMP ALIGNMENT .....	10
PUMP STATOR CHANGES .....	12
OVERDRIVE BAND CHANGES .....	14
OVERRUN CLUTCH RETURN SPRINGS AND RETAINER DESTROYED .....	16
NO MOVEMENT IN OVERDRIVE RANGE .....	20
OVERDRIVE SPRAG CHANGES .....	21
OVERDRIVE CENTER SHAFT CHANGES .....	24
SUN GEAR, SUN GEAR SHELL, DIRECT CLUTCH DRUM, FORWARD CLUTCH DRUM, AND CENTER SUPPORT CHANGES .....	29
FRONT PLANETARY GEARSET CHANGES .....	38
REAR PLANETARY CARRIER AND LUBE CIRCUIT CHANGES .....	43
THRUST WASHER LOCATION CHARTS .....	52
REAR END PLAY CHECK "WITHOUT" SNAP SHELL .....	58
REAR END PLAY CHECK "WITH" SNAP SHELL .....	60
CHECKBALL LOCATIONS (ALL MODELS) .....	64
VALVE BODY AND SPACER PLATE IDENTIFICATION .....	69
MANUAL VALVE ADJUSTMENT .....	78
UPDATED MANUAL VALVE .....	80
INTERMEDIATE AND OVERDRIVE SERVO IDENTIFICATION .....	88
COOLER LINE FITTINGS CHANGE .....	97
GOVERNOR APPLICATION AND IDENTIFICATION CHARTS .....	98
TRANSMISSION MODEL IDENTIFICATION .....	102

AUTOMATIC TRANSMISSION SERVICE GROUP  
9200 S. DADELAND BLVD. SUITE 720  
MIAMI, FLORIDA 33156  
(305) 670-4161

**A4LD BELL HOUSING IDENTIFICATION**




Figure 2

**2.8 LITER**

<b>1 SOLENOID</b>	<b>2 SOLENOIDS</b>	<b>MODEL</b>
1985 - 1987	N/A	2WD / 4WD RANGER
1985 - 1987	N/A	BRONCO II
1985 - 1987	N/A	AEROSTAR

**2.9 LITER**

<b>1 SOLENOID</b>	<b>2 SOLENOIDS</b>	<b>MODEL</b>
N/A	1988 - UP	2WD / 4WD RANGER
N/A	1988 - 1990	2WD / 4WD BRONCO II
1987 ONLY	1988 - 1990	MERKUR SCORPIO

## BELL HOUSING / PUMP ALIGNMENT

When assembling the pump body to the bell housing, a pump alignment tool must be used (Refer to Figure 10). Using the torque converter, will not produce proper pump alignment. If an alignment tool is not used, several problems may occur, such as:

- (1) PUMP GEARS BREAKING
- (2) PUMP WHINE
- (3) IRREGULAR BUSHING WEAR
- (4) IRREGULAR CONVERTER HUB WEAR
- (5) FRONT SEAL LEAK OR BLOW OUT

Another concern that may be attributed to the above listed problems, is replacement of the front pump bushing in the bell housing. At the factory, Ford puts an oversized bushing in the bell housing and then bores the bushing to the proper size, and establish the centerline. When a new bushing is installed, (possibly off center) pump alignment may not be possible. Ford Motor Company recommends using a new bell housing if bushing replacement is necessary. Aftermarket exchange bell housings with line bored bushings are also available.

PUMP ALIGNMENT  
TOOL  
FORD PART NUMBER  
T74P-77103-X




Figure 10

# Technical Service Information

---

**PREVIOUS DESIGN BAND & STRUT  
BAND ADJUSTMENT= 2.0 TURNS**




Figure 15

## NO MOVEMENT IN THE OVERDRIVE RANGE

**COMPLAINT:** Vehicle will not move in the overdrive range, but will move in D3, 2, and 1. Another common complaint is a flair-up on a 4-3 kick down.

**CAUSE:** The cause may be the overdrive sprag in backwards or not holding (See Figure 21).

**CORRECTION:** Replace the overdrive sprag, and inspect the inner and outer sprag races for wear or damage.




Figure 21

## CENTER SUPPORT THRUST WASHER FAILURE

**COMPLAINT:** Failure of the selective #4 thrust washer between the center support and the direct drum.

**CAUSE:** The cause may be lack of lubrication to the #4 thrust washer.

**CORRECTION:** Drill a new lube hole in the center support. Measure 0.500" up from the bottom of the existing hole, drill a 0.086" hole all the way through the center support (See Figure 28).




Figure 28

# Technical Service Information

---

## INTERCHANGEABILITY:


- (1) The **1st Design 3 pinion aluminum** front planetary carrier system, as shown in Figure 43, is recommended for nothing larger than 2.3L engine models. The 1st Design 3 pinion aluminum front planetary carrier is no longer serviced by Ford Motor Co. It now upgrades to the latest 3rd Design 6 pinion steel front planetary carrier system, which comes as a service package and includes all necessary hubs and washers to make it compatible, and is available under OEM part number F0TZ-7A398-E.
- (2) The **2nd Design 4 pinion steel** front planetary carrier system, as shown in Figure 43, with the 1.580" inside diameter ring gear hub, the number 7 thrust bearing, the number 6 "Top Hat" thrust washer **WILL** retro-fit back on all models, except 4.0L engine models, but all parts listed above must be used as an assembly (See Figure 43). The 2nd Design 4 pinion steel front planetary carrier is no longer serviced by Ford Motor Co. It now upgrades to the latest 3rd Design 6 pinion steel front planetary carrier system, which comes as a service package and includes all necessary hubs and washers to make it compatible, and is available under OEM part number F0TZ-7A398-E.
- (3) The **3rd Design 6 pinion steel**, 4.0L engine front planetary system, as shown in Figure 43, with the 1.580" inside diameter ring gear hub, the number 7 thrust bearing, number 6 (3 Piece) thrust bearing, and bushing (7D090) **WILL** retro-fit back on all previous models, but the parts listed above are **mandatory on 4.0L models** (See Figure 43).

## SERVICE INFORMATION:


<b>3 Piece Thrust Bearing, 6 Pinion Steel Front Carrier</b> .....	F3TZ-7D234-A
<b>Washer (7D090), 6 Pinion Steel Front Carrier</b> .....	F0TZ-7D090-A
<b>Service Package, 6 Pinion Steel Front Carrier</b>	
(Includes the following:)	
Front Planetary Assembly (7A398)	
Number 7 Thrust Bearing (7F374)	
Front Ring Gear Hub, 3rd Design (7B067)	
Forward Clutch Thrust Washer (7D090)	
3 Piece Thrust Bearing Assembly (7D234) .....	F0TZ-7A398-E

# Technical Service Information


**"1ST DESIGN"  
REVERSE DRUM  
WITH ROLLER CLUTCH**



**REQUIRES THE "2ND DESIGN"  
10 LUG REAR CARRIER**



**"2ND DESIGN"  
REVERSE DRUM  
WITH SPRAG**



**REQUIRES THE "3RD DESIGN"  
MULTIPLE LUG REAR CARRIER**




Figure 46

*AUTOMATIC TRANSMISSION SERVICE GROUP*





**CHECK BALL LOCATION  
SINGLE SOLENOID VALVE BODY  
SCORPIO / MERCUR ONLY**




Figure 63

## FORD A4LD

### VALVE BODY AND SPACER PLATE IDENTIFICATION

**COMPLAINT:** There have been many minor changes in several of the valve trains in the valve bodies on the A4LD transmission over the years, which also affects the compatibility of the spacer plate for the valve body you are using. Mis-matching these parts will create a wide variety of different complaints, depending on how they have been mis-matched.

**CAUSE:** Mis-matching of the valve body and spacer plates. Not all will interchange.

**CORRECTION: BORE 211, 1ST DESIGN: (1-2 TRANSITION VALVE)**

This bore contains the 1-2 Transition Valve and is located as shown in Figure 67. Notice the location of the No. 2 retainer in valve body is also shown in Figure 67. Figure 68 shows the "Large Hole" spacer plate that is required on the valve body with the 1st design bore 211. Figure 68 also identifies the holes that were eliminated on the two solenoid valve bodies.

**BORE 211, 2ND DESIGN: (1-2 TRANSITION VALVE)**

The 2nd design valve train has eliminated two springs and incorporated two spool valves into one, as shown in Figure 69. Figure 70 shows the "Small Hole" spacer plate that is required with the 2nd design line-up in bore 211.

**Note:** The 1st design bore 211 parts are not compatible with the 2nd design valve body casting, because the orifice control valve and the 1st design valve body bore are smaller in diameter

**BORE 207, 1ST DESIGN: ("WITHOUT" REVERSE ENGAGEMENT VALVE)**

Figure 71 shows the correct line-up for this bore, and the No. 2 retainer location in the valve body casting. Figure 72 shows the "Slot" in the spacer plate that is required for the 1st design bore 207, "Without" reverse engagement valve.

**BORE 207, 2ND DESIGN: ("WITH" REVERSE ENGAGEMENT VALVE)**

This is when the reverse engagement control valve was added to bore 207, as shown in Figure 73, and also shows the location of the No. 2 retainer in the valve body casting and the direction of the bore plugs. Figure 74 shows the "3 Hole" spacer plate that is required on valve bodies containing the reverse engagement control valve.

**Note:** Valve body castings are also different in the worm track area, when it comes to bore 207. Compare the inset in Figure 71 to the inset in Figure 73, and you will see the difference in the passages, which *will not* allow you to install reverse engagement valve into a 1st design valve body casting.

# Technical Service Information

## "SMALL HOLE" SPACER PLATE REQUIRED WITH 2ND DESIGN BORE 211 (1-2 TRANSITION VALVE)




Figure 70




Figure 75

# Technical Service Information

## ENGINE STALLS ON FORWARD OR REVERSE ENGAGEMENT

**COMPLAINT:** Engine stalls when the selector is placed into forward or reverse.

**CAUSE:** The cause may be a broken converter clutch shuttle valve spring.

**CORRECTION:** Replace the broken converter clutch shuttle valve spring with updated spring (See Figure 81).

**SERVICE INFORMATION:**

Shuttle Valve Spring.....E5TZ-7L490-A




Figure 81



# Technical Service Information

## INTERMEDIATE BAND STRUT IDENTIFICATION

### 1990 MODEL YEAR

MODEL APPLICATION	ENGINE	SERVO COVER	PISTON & ROD ASSEMBLY	SERVO SPRING	SERVO LEVER	LEVER I.D.
90GT-TAA, TBA	2.3L-(EFI)	90GT-EB	90GT-E1A	83DT-AA (GREEN)	84GT-EB	E
90GT-TCA	2.3L-(EFI)	90GT-FB	90GT-F1A	80DT-AA (BLUE)	90GT-DB	D
90GT-GAA, GBA, GCA	2.3L-(EFI)	90GT-FB	90GT-F1A	84DT-AA (YELLOW)	90GT-DB	D
90GT-KAA, LAA, LCA, MAA, NAA	2.9L-(EFI)	90GT-DB	90GT-D1A	74DT-AB (ORANGE)	84GT-AB	A
90GT-RAA, SAA RBA, SBA	3.0L-(EFI)	90GT-FB	90GT-F1A	83DT-AA (GREEN)	84GT-AB	A
90GT-EAA, FAA, CAA, EBA, FBA, DAA	4.0L-(EFI)	84DT-BB	83GT-B1A	74DT-AB (ORANGE)	84GT-AB	A
90GT-ADA, ADD AAA,AEA,AEE,BAA	4.0L-(EFI)	84DT-BB	83GT-B1A	74DT-AB (ORANGE)	84GT-AB	A

Figure 90

### 1991 MODEL YEAR

MODEL APPLICATION	ENGINE	SERVO COVER	PISTON & ROD ASSEMBLY	SERVO SPRING	SERVO LEVER	LEVER I.D.
91GT-MUA, MUB	2.3L-(EFI)	90GT-FB	90GT-F1A	80DT-AA (BLUE)	80GT-DB	D
91GT-TPA, TPB	2.3L-(EFI)	90GT-FB	90GT-F1A	84GT-AA (YELLOW)	90GT-DB	D
91GT-RAA, RBA	2.9L-(EFI)	90GT-DB	90GT-D1A	74DT-AB (ORANGE)	84GT-AB	A
91GT-AEA, AEB, AEC, AED, RCA, RDA	2.9L-(EFI)	90GT-FB	90GT-F1A	83DT-AA (GREEN)	84GT-AB	A
91GT-GAA,HAA, KAA,LAA,MAA,NAA SAA, SBA, SCA, SDA, SEA, SFA	4.0L-(EFI)	84DT-BB	83DT-B1A	74DT-AB (ORANGE)	84GT-AB	A
91GT-AAA, BAA, DAA, EAA	4.0L-(EFI)	84DT-BB	83DT-B1A	84GT-AA (YELLOW)	84GT-AB	A

Figure 91