

01 Foreword / Safety instructions

02 Service Data

03 Tools

04 Undercarriage

05 Superstructure

06 Diesel engine

07 Gear boxes

08 Hydraulic system

09 Electrical system

10 Equipment

Fittings, pipes and hoses

11 Welding for maintenance and repair

Sealing, protective, checking and cleaning agents

12

FUNDAMENTAL SAFETY INSTRUCTIONS

For carrying out overhead assembly work always use specially designed or otherwise safety-oriented ladders and working platforms. Never use machine parts as a climbing aid.

Wear a safety harness when carrying out maintenance work at greater heights.

Keep all handles, steps, handrails, platforms, landings and ladders free from dirt, snow and ice.

Clean the machine, especially connections and threaded unions, of any traces of oil, fuel or preservatives before carrying out maintenance/repair. Never use aggressive detergents. Use lint-free cleaning rags.

Before cleaning the machine with water, steam jet (high-pressure cleaning) or detergents, cover or tape up all openings which - for safety and functional reasons - must be protected against water, steam or detergent penetration. Special care must be taken with electric motors and switchgear cabinets.

Ensure during cleaning of the machine that the temperature sensors of the fire-warning and fire-fighting systems do not come into contact with hot cleaning agents as this might activate the fire-fighting system.

After cleaning, remove all covers and tapes applied for that purpose.

After cleaning, examine all fuel, lubricant, and hydraulic fluid lines for leaks, loose connections, chafe marks and damage. Any defects found must be rectified without delay.

Always tighten any screwed connections that have been loosened during maintenance and repair.

Any safety devices removed for set-up, maintenance or repair purposes must be refitted and checked immediately upon completion of the maintenance and repair work.

Ensure that all consumables and replaced parts are disposed of safely and with minimum environmental impact.

Warning of special dangers

Electric energy

Use only original fuses with the specified current rating. Switch off the machine immediately if trouble occurs in the electrical system.

When working with the machine, maintain a safe distance from overhead electric lines. If work is to be carried out close to overhead lines, the working equipment must be kept well away from them. Caution, danger! Check out the prescribed safety distances.

If your machine comes into contact with a live wire

- do not leave the machine
- drive the machine out of the hazard zone
- warn others against approaching and touching the machine
- have the live wire de-energized
- do not leave the machine until the damaged line has been safely de-energized.

The electrical equipment of machines is to be inspected and checked at regular intervals. Defects such as loose connections or scorched cables must be rectified immediately.

Gas, dust, steam and smoke

Operate internal combustion engines and fuel-operated heating systems only on adequately ventilated premises. Before starting the machine on enclosed premises, make sure that there is sufficient ventilation.

Observe the regulations in force at the respective site.

Carry out welding, flame-cutting and grinding work on the machine only if this has been expressly authorized, as there may be a risk of explosion and fire.

Before carrying out welding, flame-cutting and grinding operations, clean the machine and its surroundings from dust and other inflammable substances and make sure that the premises are adequately ventilated (risk of explosion).

SERVICE DATEN / SERVICE DATA

Umrechnung von Newtonmeter "Nm" in Foot Pounds "ft.lb." Conversion from newtonmeter "Nm" into foot pounds "ft.lb."

Nm	0	1	2	3	4	5	6	7	8	9
10	7.376	8.113	8.851	9.588	10.326	11.063	11.801	12.539	13.276	14.014
20	14.751	15.489	16.226	16.964	17.701	18.439	19.177	19.914	20.652	21.389
30	22.127	22.864	23.602	24.339	25.077	25.815	26.552	27.290	28.027	28.765
40	29.502	30.240	30.978	31.715	32.453	33.190	33.928	34.665	35.403	36.140
50	36.878	37.616	38.353	39.091	39.828	40.566	41.303	42.041	42.778	43.516
60	44.254	44.991	45.729	46.466	47.204	47.941	48.679	49.417	50.154	50.892
70	51.629	52.367	53.104	53.842	54.579	55.317	56.055	56.792	57.530	58.267
80	59.005	59.742	60.480	61.217	61.955	62.693	63.430	64.168	64.905	65.643
90	66.380	67.118	67.856	68.593	69.331	70.068	70.806	71.543	72.281	73.018
100	73.756	74.494	75.231	75.969	76.706	77.444	78.181	78.919	79.656	80.394
110	81.132	81.869	82.607	83.344	84.082	84.819	85.557	86.295	87.032	87.770
120	88.507	89.245	89.982	90.720	91.457	92.195	92.933	93.670	94.408	95.145
130	95.883	96.620	97.358	98.095	98.833	99.571	100.308	101.046	101.783	102.521
140	103.258	103.996	104.734	105.471	106.209	106.946	107.684	108.421	109.159	109.896
150	110.634	111.372	112.109	112.847	113.584	114.322	115.059	115.797	116.534	117.272
160	118.010	118.747	119.485	120.222	120.960	121.697	122.435	123.173	123.910	124.648
170	125.385	126.123	126.860	127.598	128.335	129.073	129.811	130.548	131.286	132.023
180	132.761	133.498	134.236	134.973	135.711	136.449	137.186	137.924	138.661	139.399
190	140.136	140.874	141.612	142.349	143.087	143.824	144.562	145.299	146.037	146.774
200	147.512	148.250	148.987	149.725	150.462	151.200	151.937	152.675	153.412	154.150
210	154.888	155.625	156.363	157.100	157.838	158.575	159.313	160.051	160.788	161.526
220	162.263	163.001	163.738	164.476	165.213	165.951	166.689	167.426	168.164	168.901
230	169.639	170.376	171.114	171.851	172.589	173.327	174.064	174.802	175.539	176.277
240	177.014	177.752	178.490	179.227	179.965	180.702	181.440	182.177	182.915	183.652
250	184.390	185.128	185.865	186.603	187.340	188.078	188.815	189.553	190.290	191.028
260	191.766	192.503	193.241	193.978	194.716	195.453	196.191	196.929	197.666	198.404
270	199.141	199.879	200.616	201.354	202.091	202.829	203.567	204.304	205.042	205.779
280	206.517	207.254	207.992	208.729	209.467	210.205	210.942	211.680	212.417	213.155
290	213.892	214.630	215.368	216.105	216.843	217.580	218.318	219.055	219.793	220.530
300	221.268	222.006	222.743	223.481	224.218	224.956	225.693	226.431	227.168	227.906
310	228.644	229.381	230.119	230.856	231.594	232.331	233.069	233.807	234.544	235.282
320	236.019	236.757	237.494	238.232	238.969	239.707	240.445	241.182	241.920	242.657
330	243.395	244.132	244.870	245.607	246.345	247.083	247.820	248.558	249.295	250.033
340	250.770	251.508	252.245	252.983	253.721	254.458	255.196	255.933	256.671	257.408
350	258.146	258.884	259.621	260.359	261.096	261.834	262.571	263.309	264.046	264.784
360	265.521	266.259	266.997	267.734	268.472	269.209	269.947	270.684	271.422	272.159
370	272.897	273.635	274.372	275.110	275.847	276.585	277.323	278.060	278.798	279.535
380	280.273	281.010	281.748	282.485	283.223	283.960	284.698	285.436	286.173	286.911
390	287.648	288.386	289.123	289.861	290.598	291.336	292.074	292.811	293.549	294.286
400	295.024	295.761	296.499	297.237	297.974	298.712	299.449	300.187	300.924	301.662
410	302.399	303.137	303.875	304.612	305.350	306.087	306.825	307.562	308.300	309.038
420	309.775	310.513	311.250	311.988	312.725	313.463	314.200	314.938	315.676	316.413
430	317.151	317.888	318.626	319.363	320.101	320.838	321.576	322.313	323.051	323.789
440	324.526	325.264	326.001	326.739	327.477	328.214	328.952	329.689	330.427	331.164
450	331.902	332.639	333.377	334.115	334.852	335.590	336.327	337.065	337.802	338.540
460	339.278	340.015	340.753	341.490	342.228	342.965	343.703	344.440	345.178	345.916
470	346.653	347.391	348.128	348.866	349.603	350.341	351.078	351.816	352.553	353.291
480	354.029	354.766	355.504	356.241	356.979	357.717	358.454	359.192	359.929	360.667
490	361.404	362.142	362.879	363.617	364.354	365.092	365.830	366.567	367.305	368.042
500	368.780	369.517	370.255	370.992	371.730	372.468	373.205	373.943	374.680	375.418
510	376.156	376.893	377.631	378.368	379.106	379.843	380.581	381.318	382.056	382.793
520	383.531	384.269	385.006	385.744	386.481	387.219	387.957	388.694	389.432	390.169
530	390.907	391.644	392.382	393.119	393.857	394.594	395.332	396.070	396.807	397.545
540	398.282	399.020	399.757	400.495	401.232	401.970	402.708	403.445	404.183	404.920
550	405.658	406.396	407.133	407.871	408.608	409.346	410.083	410.821	411.558	412.296
560	413.033	413.771	414.509	415.246	415.984	416.721	417.459	418.196	418.934	419.671
570	420.409	421.147	421.884	422.622	423.359	424.097	424.834	425.572	426.310	427.047
580	427.785	428.522	429.260	429.997	430.735	431.472	432.210	432.948	433.685	434.423
590	435.160	435.898	436.635	437.373	438.111	438.848	439.586	440.323	441.061	441.798
600	442.536	443.273	444.011	444.749	445.486	446.224	446.961	447.699	448.436	449.174
610	449.911	450.649	451.386	452.124	452.862	453.599	454.337	455.074	455.812	456.550
620	457.287	458.025	458.762	459.500	460.237	460.975	461.712	462.450	463.187	463.925
630	464.663	465.400	466.138	466.875	467.613	468.350	469.088	469.826	470.563	471.301
640	472.038	472.776	473.513	474.251	474.989	475.726	476.464	477.201	477.939	478.676
650	479.414	480.151	480.889	481.626	482.364	483.102	483.839	484.577	485.314	486.052
660	486.790	487.527	488.265	489.002	489.740	490.477	491.215	491.952	492.690	493.427
670	494.165	494.903	495.640	496.378	497.115	497.853	498.590	499.328	500.065	500.803
680	501.541	502.278	503.016	503.753	504.491	505.229	505.966	506.704	507.441	508.179
690	508.916	509.654	510.391	511.129	511.866	512.604	513.342	514.079	514.817	515.554
700	516.292	517.030	517.767	518.505	519.242	519.980	520.717	521.455	522.192	522.930

SERVICE DATA

Zulässiges Lagerspiel Permissible bearing play

Drehverbindung Swing bearing	EC 130 Nr. / No. 11 701 -
Zahnflankenspiel min. Drehverbindung - Schwenkgetrieberitzel Min. flank play swing bearing slew pinion	0,3 ^{+0,2} mm 0.01 ^{+0,008} inch

Anziehdrehmomente Tightening torques

		EC 130 Nr. / No. 11 701 -
Laufrolle Bottom roller	Gewindegröße Thread size	M 16 ¹⁾ / 12.9 / SW 24
	Sach-Nr. Part No.	73171578
	Anziehdrehmoment Tightening torque	330 Nm 243 lbft
Stützrolle Top roller	Gewindegröße Thread size	M 16 / 10.9 / SW 24
	Sach-Nr. Part No.	73176997
	Anziehdrehmoment Tightening torque	250 Nm 185 lbft
Bodenplatte Track pad	Gewindegröße Thread size	M 14 x 1,5 ¹⁾ / 12.9 / SW 22
	Sach-Nr. Part No.	3-Steg-Bodenplatte Triple-grouser truck-pad 73177002
	Anziehdrehmoment Tightening torque	235 Nm 174 lbft
Fahrgetriebe Final drive	Gewindegröße Thread size	M 16 x 45 / 10.9 / SW 24
	Sach-Nr. Part No.	73172206
	Anziehdrehmoment Tightening torque	250 Nm 184 lbft
Kettenrad- Fahrgetriebe Sprocket- final drive	Gewindegröße Thread size	M 16 x 55 ²⁾ / 10.9 / SW 24
	Sach-Nr. Part No.	73177037
	Anziehdrehmoment Tightening torque	340 Nm 251 lbft

¹⁾ Sechskantschraube, leicht geölt
Hex. hd. screw. lightly oiled

²⁾ Schrauben mit flüssiger Schraubensicherung
z.B. Loctite 242, 243.
Screws with liquid screw fixer, e.g. Loctite 242,
243

Sprocket

2800529

The sprocket is bolted to the travel gearbox.

- Assembly requirements

Removal and installation of the sprocket is possible with installed travel gearbox.

- Tightening bolts

The thread and the contact surface of the bolt head are to be slightly oiled.

- Contact surface

Check the contact surface of sprocket and travel gearbox for damage and clean with thinner (Part-no. 73171477) from paint and grease. All contact surfaces must be cleaned down to the bright metal and be dry and free from grease.

- Thread holes

All thread holes in the travel gearbox have to be cleaned with compressed air, carefully checked for paint, rust and damage. If required the threads are to be taped again.

- Adhesive

When the sprocket is prepared for installation apply a thin layer of adhesive (Part-no. 73176144) onto one of the contact surfaces.

Apply the adhesive appr. 10 mm clear of the thread holes. When assembling the sprocket no adhesive must reach the thread holes. The penetration of adhesive into the thread hole results in increased friction and thus in wrong tightening of the bolts.

- Installation



CAUTION

Start assembly immediately after application of the adhesive.

Hardening of the adhesive begins after joining the metal surfaces under the exclusion of air and is generally completed after approx. 48 hours at an ambient temperature of 68°F.

The hardening process begins only after a considerable initial delay so that the fitting operations may extend over a period of 8 hours maximum.

At temperatures of -50°F it is necessary to spray an activator (Part no. 73176145) onto the second contact surface, i.e. the one without adhesive.

The bolts have to be tightened crosswise with the required torque.

Reassembling the Traveling Gearbox

- Thoroughly remove any paint and grease from the seating surfaces (A and B, Fig. 1) of the undercarriage frame, the sprocket and the traveling gearbox with thinner (Item No. 73171477). Then check for damage.
Seating surfaces must be bright, dry and free of grease.
- Join the sprocket and the traveling gearbox and align them.
- Fix the sprocket to the gearbox by four bolts (2, Fig. 1). Tighten the bolts by hand.
- To make easier joining the traveling gearbox into the frame, screw one M 20 x 1.5 stud bolt into a tapped hole in the longitudinal beam for guidance.
- Apply a ring of adhesive (Item No. 73176144) of about 1 mm in thickness around each tapped gearbox bolt hole.
- Attach lifting tackle to the bore in the sprocket (see arrow, Fig. 3), bring to fitting position and align.
- Secure the traveling gearbox to the frame by turning in a few hexagon bolts (3, Fig. 1 - 3). Place sleeves (4) over all slightly oiled gearbox bolts (3), turn them in and tighten them.
Proceed crosswise, mark tightened bolts.
- Remove the sprocket bolts (2) and pull off the chain wheel. Apply adhesive (Item No. 73176144) around each tapped hole.



CAUTION

Apply the adhesive at some distance to the holes so that no adhesive can get to the threads when the parts are joined.

Do not apply the adhesive before the sprocket and the gearbox are ready for assembling.

- Mount the chain wheel.

Turn the slightly oiled bolts (2, Fig. 4) in and tighten them.

Proceed crosswise, mark tightened bolts.

- Re-close the track.




Fig. 4

- Re-connect the hydraulic lines (Fig. 2) and re-fit the traveling gearbox guard.
- Bleed the parking brake. □

SWING GEARBOX




Fig. 13

Drive the flange mortised at five places around the circumference to secure the grooved ring nut out of the tothing by means of a pointed punch (scribing iron).




Fig. 14

Place the swing pinion with its housing into fitting aid (S4) or clamp it in a vise with protective plates between the jaws and the pinion. Slacken the grooved ring nut with fitting wrench (S7).




Fig. 15

Screw off the grooved nut with a caliper wrench. Remove the adjusting shims and the Nilos ring. Withdraw the O-ring from the housing.




Fig. 16

Place the housing on the support and press the pinion shaft out of its bearings.




Fig. 3

Cover (S2)

P/N: 73176728

Material: S355J2G3 (St52-3)




Fig. 7

Oil coolers with fan drive (20, 21, Fig. 7)

The return-flow oil from the working- and travel hydraulics flows through the hydraulic oil cooler (20). Additionally, the return oil from the fan drive unit flows through the oil cooler to the filter chamber in the hydraulic reservoir.

The fan is driven by a gear motor with control valve (21). The fan drive is equipped with a pressure relief and a replenishing valve.

□

Piston rod and piston

Dismantling and checking:

- Drain hydraulic oil from the cylinder. Collect escaping oil in a suitable recipient.
- Remove bearing eye (1, Fig. 14) and guide (7).




Fig. 14

- Attach piston rod (8, Fig. 15) with fitting ring (D) to lifting tackle, withdraw carefully from cylinder barrel and place on a suitable working surface.




Fig. 15

- Remove the plastic guide rings (20, Fig. 16) and the OK piston seal (21).




Fig. 16

- Check the piston with piston rod and dampeners and the cylinder barrel carefully for damage and wear. Check the cylinder barrel also for signs of widening. Replace all defective parts. The plastic guide rings, the protective elements and the OK piston seal must always be replaced.

POWER GENERATION

If the fact is exploited that a magnetic field is formed round a conductor when a current flows through it, it is relatively easy to build an electric generator. The principle is shown in the diagram below. Windings (2) supplied with direct current (3) are mounted on a rotor (1), resulting in a magnetic field (4). The windings (6) mounted on the stator (5) of our theoretical generator are cut by the magnetic field (4) of the rotor as the rotor is turned. This generates electric voltage in the stator winding.




Fig. 1

Power generation in motor vehicles

Some years ago, so-called d.c. generators were installed in motor vehicles. Because of their size and output, they were replaced by a.c. generators.

In an a.c. generator, three alternating currents, each phase-shifted by 120° , are generated. This alternating current is rectified in the vehicle by means of diodes, and we have direct current. The direct current is regulated to the required charging current with a regulator. The resulting direct current is needed to recharge the battery, i.e. the battery is recharged while the engine is running.




Fig. 2




Fig. 3




Fig. 3

3281861

FLANGE COUPLINGS WITH SAE BOLT PATTERN

Flanged pipe couplings - Flanit system (F-system)

These couplings are for pipes between $\varnothing 25 \times 3$ and $\varnothing 50 \times 2$.

Fig. 1 shows the components of the F-system; Fig. 2 a finished coupling. The components are:

- 1 - Connection surface
- 2 - Seal ring
- 3 - F-ring (wedge ring)
- 4 - Flange
- 5 - Double-hex bolt
- 6 - Pipe

In the F-system, the wedge ring (F-ring) is pushed onto the pipe.

The secure connection of wedge ring and pipe is achieved by tightening the double-hex bolts. A pre-assembly device is not needed.

Gap dimension "L" is used to check whether the connection has been correctly established.




Fig. 1




Fig. 2

Flanged pipe couplings - Zako system (Z-system)

These couplings are used for pipes $\varnothing 50 \times 6$ (1", 6000 psi).

Fig. 1 shows the components of the Z-system; Fig. 2 a finished coupling. The components are:

- 1 - Connection surface
- 2 - Seal ring
- 3 - Z-ring (wedge ring)
- 4 - Flange
- 5 - Double-hex bolt
- 6 - Pipe




Fig. 1




Fig. 2

FUNDAMENTALS

1.4.4 Notch effects

Depending on their shape, notches have different notch or influencing factors.

The influence of notch factors on the fatigue strength of a component is shown in the graph (fig. 18).




Fig. 18

Location and shape of curves W, O, 1, 2, 3 and 4 refer to:

material: EN 10025: S355J2G3
 no. of load cycles: $2 \cdot 10^6$ (2 million)
 i.e. of high fatigue strength
 group of stress intensities: small, medium and high stresses with approx. the same frequency

Possible notches (mechanical and metallurgical) in the seams of butt-weld joints:

Weld seam	Notch factor	Description
	W	Unaffected material; no weld seam
	O	Ideal weld seam; root pass gouged, surface levelled, stress-relief annealed, preheated for welding (if required)
	1	Practical weld seam; root pass gouged, surface levelled, preheated for welding (if required)
	2	Root pass cleaned and capped, otherwise untreated
	2	Welded on backing strip (cf. para. 3.6.1.3)
	3	Not capped; root failure probable
	3	Welded on backing strip (cf. para. 3.4.3)
	4	Seamwelded from one side; root pass defective

6001911

For a notch factor of "O", practically the only effects to be expected are from metallurgical notches.

HEAT TREATMENT OF MATERIALS

6.6 Treatment of filler metals

Filler metals, such as rod electrodes, welding wire coils, welding powder and welding rods, must be stored so as to prevent them from deteriorating. This is only possible in heated rooms at abt. 30°C (90°F) and a relative humidity of below 50 %.

The packages must remain closed until the material is used. Unused filler metals must be repacked and brought back into the storage room.

Why is this necessary?

- Coatings of rod electrodes or welding powders used for submerged-arc welding are hygroscopic, i.e. they absorb ambient humidity. Without protection, these materials get moist or even wet. During welding, the hydrogen and oxygen contained in the water penetrate into the weld metal and make it brittle.

Rod electrodes from new or already opened packages must be redried and stored in a heated box until they are used.

Manufacturers of rod electrodes issue instructions for redrying.

Reference values for electrodes with coating type B:

2h at 350°C (660°F)

3h at 250°C (480°F)

4h at 200°C (390°F)

There is often a failure to take this tiresome but necessary action.

Assistance is now offered by the manufacturers of rod electrodes.

The rod electrodes are supplied in site-resistant, moisture-impermeable special packs.

Redrying and keeping warm are no longer necessary if the rod electrodes are used within 8 hours (1 working shift) of the pack being opened. Hydrogen content < 5 ml/100 g weld metal.

One box (package) therefore contains a number of individual packs suitable for use by one welder. The rod electrodes are vacuum-packed firmly together in shrink film.

Single rods must not be movable if the packaging is intact. Prior to opening the pack, it must have been brought to the ambient temperature at the application site.

Wet rod electrodes must be destroyed. In spite of redrying they can never again be used for welding.

- Wet welding wires or welding rods are subject to corrosion. The copper coating offers only a temporary protection against corrosion.

Rust, a chemical compound of iron and oxygen, introduces unwanted amounts of oxygen into the weld metal, with the result that the material gets brittle.

Corroded welding wire contaminates the wire guide tubes. This leads to an earlier wear of these elements.

Corroded welding wires and welding rods therefore have to be discarded.

6.7 Temperature monitoring

For temperature monitoring during heat treatment processes, the following equipment is recommended:

- Electrical temperature probes:

These are easy to handle and provide an exact temperature reading on an analog or a digital display.

Manufacturers of rod electrodes issue instructions for redrying.

- Adherent thermometers:

Thermometers with an analog display, which are attached with magnets to the component.

- Temperature-indicating crayons:

These crayons are used to make a mark on the component to be heated. When the desired temperature range is reached, the colour of the mark changes.

In principle, this procedure is very simple.

It requires, however, some experience with the crayons to perceive the changing of the colour.